# Westhertzanon Assistance Program

# Work Order (Bid Form)

### **WORK ORDER INFORMATION**

Work Order Name: 14014SO2086Work Order Type: WeatherizationAudit Name: 14014SO2086

#### **CLIENT INFORMATION**

Client Name: Address:

**Client ID:** 14014SO2086 LEWISBURG, TN 37091

Alt. Client ID: MARSHALL

# **AGENCY INFORMATION**

Agency: SOUTH CENTRAL HUMAN RESOURCE AGENCY Agency Phone: (931) 433-7182

Address: 1437 WINCHESTER HIGHWAY Fax: (931) 438-0074

Company Name & License Number:	
Contractor's Signature:	

## **COMMENT**

Client Name:
Client ID: 14014SO2086
Alt. Client ID: MARSHALL

Work Order (Bid Form)
Work Order Name: 14014SO2086

Report Run On: 5/14/2010

DOE Weatherization Assistant Version 8.5.0 Page 1 of 7

	Measure	1	Infilt	ratior	n Red	dctn						Com	oonei	nts				In	specte
C	2. DUCTS OFF LAYING ON GROUND AND HAS MOLD VISIBLE, REPLACE DUCTS AND SEAL REGISTERS AND RETURN WITH MASTIC 3. REPLACE BROKEN GLASS PANE IN FRONT DOOR / W/S AND D/S AND INSTALL NEW STORM HARDWARE 4. W/S AND INSTALL NEW STORM HARDWARE ON BACK DOOR 5. W/S AND INSTALL NEW STORM HARDWARE ON SIDE DOOR 6. REPLACE PANE ON KITCHEN DOOR 7. REPAIR HOLE IN BATHROOM WALL																		
												Es	timate	d			Actual		
#	Material /	Lal	oor	Desc	riptio	n / Coı	mment		Units	(	Qty	Unit	Cost	Tota	1	Qty	Unit Cos	t	Total
1	Miscellar Supplies	ieoi	JS	Infilt	ration	Redu	ction		Each		1								
2	Labor			LAB	OR				Hour										
C	Other Detail	1																	
										Me	asur	Sub	Total:				Sub Total:		
	Field Note	es:																	

Measure 2 Ins	tall/Replace Heatpump			Componen	ts			Inspected
	ACE WITH ELECTRIC UN WIRE FROM BOX	IT - HASN	N'T WC	RKED IN 8	YRS R	UN		
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Heating     Equipment	Heatpump - 34 kBtu/h Existing, Consult Manual J Data	Each	1					
2 Labor	Heatpump - 34 kBtu/h Existing, Consult Manual J Data	Each	1					
Other Detail						1		
						]		
			Measur	e Sub Total:		]	Sub Total:	
Field Notes:								
Measure 3 DW Comment	/H Pipe Insulation			Componen			Actual	Inspected
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DHW Pipe Insulation	Each	1					
2 Labor	DHW Pipe Insulation	Each	1					
Other Detail								
						] []		
			Measur	e Sub Total:		]]	Sub Total:	
Field Notes:								

Equipment	<i>Units</i> Each					1	
Hot Water DHW Tank Insulation Equipment			Estimated			Actual	
Hot Water DHW Tank Insulation Equipment		Qty	Unit Cost	Total	Qty	Unit Cost	Total
		1		- <b> </b>			
	Each	1					
ther Detail							
		Measure	Sub Total:			Sub Total:	
leasure 5 Attic Ins. R-19			Component  Estimated	ts		Actual	Inspected
Material / Labor Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
•	SqFt	1537		, ctui			
Cellulose - R-19							
Cellulose - R-19	SqFt	1537					
Cellulose - R-19  Labor Attic Insulation - Blown	SqFt	1537					
Cellulose - R-19  Labor Attic Insulation - Blown Cellulose - R-19	SqFt	1537					
Cellulose - R-19  Labor Attic Insulation - Blown Cellulose - R-19			e Sub Total:			Sub Total:	

Measure 6 Floo Comment	r Ins. R-19			Componen				Inspected
				Estimated	<del></del>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Floor Insulation - Fiberglass Batts - R-19	SqFt	1537					
2 Labor	Floor Insulation - Fiberglass Batts - R-19	SqFt	1537					
Other Detail								
			Measure	e Sub Total:			Sub Total:	
	mproper Venting (Cloth E TO METAL FLEX AND	-	•					Inspected
<b>Comment</b> CHANG	E TO METAL FLEX AND	) INSTAL	L DAMI	PER <b>Estimated</b>		Qtv	Actual	
Comment CHANG  # Material / Labor	E TO METAL FLEX AND  Description / Comment	-	•	PER		Qty		Inspected Total
<ul><li>Comment CHANG</li><li># Material / Labor</li><li>1 Health and Safety Items</li></ul>	E TO METAL FLEX AND  Description / Comment	O INSTALI Units	L DAMI	PER Estimated		Qty	Actual	
<ul><li>Comment CHANG</li><li># Material / Labor</li><li>1 Health and Safety Items</li></ul>	E TO METAL FLEX AND  Description / Comment  Metal Flex	Units Each	Qty	PER Estimated		Qty	Actual	
<ul><li>Comment CHANG</li><li># Material / Labor</li><li>1 Health and Safety Items</li><li>2 Labor</li></ul>	E TO METAL FLEX AND  Description / Comment  Metal Flex	Units Each	Qty	PER Estimated		Qty	Actual	Inspected Total
<ul><li>Comment CHANG</li><li># Material / Labor</li><li>1 Health and Safety Items</li><li>2 Labor</li></ul>	E TO METAL FLEX AND  Description / Comment  Metal Flex	Units Each	Qty	PER Estimated		Qty	Actual	
<ul><li>Comment CHANG</li><li># Material / Labor</li><li>1 Health and Safety Items</li><li>2 Labor</li></ul>	E TO METAL FLEX AND  Description / Comment  Metal Flex	Units Each	Qty 1 1	PER Estimated			Actual	

omment INSTALL	II Bathroom Exhaust F	an		Componen	ts			Inspecte
OUTSIDI	ELECTRIC EXHAUST E USING NEW WIRE F							
				Estimated			Actual	
Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety Items	Bathroom exhaust fan	Each	1					
Labor	Labor	Hour	1					
Other Detail						,		
						] []		
			Measur	e Sub Total:			Sub Total:	
Μροεμγο 10 Οτρεσ	surePelief Pining Need	lod		Componen	te			Inspecte
Measure 10 Press comment	sureRelief Piping Need	led		Componen				Inspected
comment				Estimated		Otv	Actual	
Comment  Material / Labor	SureRelief Piping Need  Description / Comment  Pressure relief piping	<b>Units</b> Each	Qty 1	•		Qty		Total
Comment  Material / Labor  Health and Safety	Description / Comment	Units	Qty	Estimated		Qty	Actual	
Material / Labor Health and Safety Items	Description / Comment Pressure relief piping	<i>Units</i> Each	<b>Qty</b> 1	Estimated		Qty	Actual	
Material / Labor Health and Safety Items Labor	Description / Comment Pressure relief piping	<i>Units</i> Each	<b>Qty</b> 1	Estimated		Qty	Actual	
Material / Labor Health and Safety Items Labor	Description / Comment Pressure relief piping	<i>Units</i> Each	<b>Qty</b> 1	Estimated		Qty	Actual	
Material / Labor Health and Safety Items Labor	Description / Comment Pressure relief piping	Units Each Hour	Qty 1 1	Estimated			Actual	

	Measure 11 Smo	ke Detector is Needed			Componen	ts			Inspected
C	omment								
					Estimated	<u> </u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Smoke / Carbon detector	Each	1					
2	Labor	Labor	Hour	1					
C	Other Detail			1			1		
L									
				Measur	e Sub Total:		,	Sub Total:	
		or Barrier Needed ement/Crawlspace)			Componen	its			Inspected
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Basement / crawlspace vapor barrier	Each	1					
2	Labor	Labor	Hour	1					
(	Other Detail			]			1		
L							]		
							] []		
E				Measur	e Sub Total:		•	Sub Total:	
	Field Notes:								
			Work O	rder Gra	nd Total:		Gran	d Total:	